

ERRATA SHEET No. 1 (for Electronic Technicians)

Engineering Division

W/OSO321:BGM

Additional sites to Maintenance Note 39, Dated June 5, 1998

General:

Errata sheet No. 1 adds five sites to appendix B, Maintenance Note 39, Section 2.6.

Effect on Other Instructions:

Maintenance Note 39

Procedure:

1. A table with five additional sites for Maintenance Note 39 is provided with information on the times to deconfigure and reconfigure the freezing rain sensor. The table provided with Errata Sheet No. 1 is to be removed and attached to EHB-11, Volume 2, Maintenance Note 39, Section 2.6, appendix B.

***Original Signed***

John McNulty

Chief, Engineering Division

W/OSO321:B.McCormick:713-1833x120:updated:6/30/99

File:K:\OSO32\OSO321\ASOS Temp\errata39.h11.wpd

spellchecked:6/30/99:src

**Site List (JUNE 1 - September 15)****Deconfigure and Power-Off: On or After June 1****Reconfigure and Power-Up: On or Before September 15****CENTRAL**

ANJ	SAULT STE. MARIE	MI
GLR	GAYLORD	MI
HTL	HOUGHTON	MI
PLN	PELLSTON	MI
TVC	TRAVERSE CITY	MI