

Errata Sheet 1 to Automated Surface Observing System (ASOS) Modification Note 38, Dated September 17, 1997.

General:

Errata sheet number 1 provides instructions to correct EHB-11, Volume 2, Section 3.6, Modification Note 38. These changes clarify information, and add Version 2.49 firmware to Single Cabinet Assemblies.

Effect on Other Instructions:

EHB-11, Volume 2, Section 3.6, pages 1-2, Appendix C, page C1 (front and back), Appendix D pages D1, D2, and D3 of Modification Note 38.

Procedure:

1. Page 1, add **"for each DCP CPU"** to the third sentence in the MOD PROCUREMENT. The corrected text should read in its entirety: "ASOS technicians will need to order ACU EPROMs S100-1A2A3-U8C, DCP EPROMs S100-2A1A2A1U29 for each DCP CPU, I/O panel feed through adapter S100-1A9J22 and an RS-422 adapter S100-1A9W77 as described in Appendix D". Add the following sentence to MOD PROCUREMENT: "Install version 2.49 EPROM's to all ASOS that have a Single Cabinet Assembly (SCA)."
2. Page 1, make a pen and ink change to the second line in the EFFECT ON OTHER INSTRUCTIONS. Strike out (Modification Note 20, including errata, Modification Note 31 and Modification 14). Add the following line in place of the line that was struck out: **"for these sites listed in Appendix D"**.
3. Page 2, make a pen and ink change to the second sentence in the PROCEDURE. Strike out (1A9W1) and replace it with **(1A9W77)**.
4. Appendix C, page C1, make the following pen and ink change to the front page. Strike out the word **Sample** and replace it with **Example**. On the back of page C1, block 15, strike out 2.47 and replace it with 2.49.

PRELIMINARY

5. *Appendix D, page D1, in the fourth column make a pen and ink change, strike out S100-1A9W1 and replace it with S100-1A9W77.*
6. Appendix D, page D2, delete line fifteen (EKN).
7. Appendix D, page D3, delete line seven (HON).


John McNulty
Chief, Engineering Division

