

Reporting Activation of the Automated Surface Observing System
(ASOS)

General

This maintenance note provides information on activation of ASOS. The instructions provided in the Technical Information Package (TIP), Maintenance Note 1, Section 2.5, on EMRS reporting are incorrect. The ASOS Program Office will report the activation of ASOS to the appropriate authority.

Effect on Other Instructions

The second sentence in the TIP, Section 4, paragraph 4.3, is to be corrected. The deactivation procedure will still be followed and reported in accordance with instructions in EHB-4.

Procedure

The TIP, Section 4, paragraph 4.3, may be corrected by pen and ink. Correct the second sentence to read, "The activation of ASOS will be reported by the ASOS Program Office, not in accordance with procedures detailed in EHB-4."

J. Michael St. Clair
Chief, Engineering Division

W/OSO321:BGMcCormick:rhz:4/22/92
disk 11,13,etc. "maint2.h11"
wp5.1 Speller