

Errata to Modification Note 47, Acquisition Control Unit Memory Firmware Version 2.60

**PROCEDURE**

1. The following corrections should be made to Modification Note 47:
  - a. *Page 8:* lines 8 and 9: Change “Enter both AOMC phone numbers, 1-800-253-4717 and 1-800-434-1133 into the AOMC PHONE NUMBER field and press the **EXIT** key” to read “Enter 1-800-253-4717 as the primary AOMC phone number and press the **EXIT** key. Leave the secondary AOMC phone number blank.”
  - b. *Page 8, line 10:* Set the following fields to:  
REPLY REQUEST to **YES**  
BUSY ATTEMPT TIME to **2**  
SEND REPLY TIME(SECS) to **020**  
RECV REPLY TIME(MINS) to **1**
  - c. *Page 15, line 23:* Add the following:

**Note:**

**Before leaving the site, ensure the ASOS voice is functioning properly.**

***Original Signed***

John McNulty  
Chief, Engineering Division

W/OSO321:W. Whisel:713-1833x156  
File:K:\OSO32\OSO321\ASOS Temps\Errata1\_Mod47.wpd  
updated:10/14/99:spellchecked:10/14/99:src