

ERRATA SHEET 1 (for Electronics Technicians)

Engineering Division

W/OSO321:AJW

Additional Information to Modification Note 21 dated August 8, 1995

General

Errata sheet number 1 provides instructions to correct EHB-11, section 3.6, page 3 of modification note 21. The reason for the change is to provide additional information after modification note 21 was published.

Effects on Other Instructions

Page 3 of modification note 21, Volume 2, EHB-11, section 2.6.

Procedures:

Add the following information:

1. Step 4 Section II Adjust the power supply.

CHANGE: Pen-and-ink change. Add the following after the third sentence:

If R11 has been adjusted fully clockwise and the Voltage is not within tolerance, the minimum acceptable voltage is 27.0 volts DC.

Add the following after the last sentence:

If the voltage is below 27.0 VDC, replace the heater power supply.

Acting Chief, Engineering Division